



# Product Safety Recall



## Do you own this product?

### GPC Asia Pacific — Kelpro Control Arms

Kelpro branded control arms to suit Toyota Hilux 7th Generation (February 2005 – September 2015), left and right side.

Part numbers:

- KCA8209
- KCA8210

Dates sold: 23 January 2024 – 5 February 2025



**Why the product is recalled:** The ball joint and outer arm may not be welded correctly, causing the ball joint to separate from the control arm.

**Hazard:** Risk of serious injury or death if the ball joint separates from the control arm whilst the vehicle is in use and causes a collision.



Consumers should immediately take their vehicle to the place where the product was installed to arrange for an inspection. Consumers will receive a free replacement of any affected control arm.



Ask our staff to find out more about the recall.

[recalls@gpcasiapac.com](mailto:recalls@gpcasiapac.com)

1300 301 072



Purchased from:

NAPA

PRA 2025/2044

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information